



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director
JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
Date: October 28, 2008

Reviewed: 26

Mine Name: Bluffdale Sand & Gravel 2	Permit Number: S/035/0027
Operator Name: Bluffdale Sand & Gravel Inc.	Inspection Date: 10/16/2008
Inspector(s): Brett Gregory for Leslie Heppler	Time: 3:30 pm
Other Participants: None	Mine Status: Proposed

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$17,000

Permit fee: Delinquent 2006-2008.

Purpose of Inspection: This was a routine annual inspection of the site.

Inspection Summary: Photos attached.

1) The annual permit fees have not been paid since 2005. The cumulative total is \$450 dollars.

Conclusions and Recommendations: All permit fees NEED to be paid.
DOGM will continue to monitor this site.

Inspector's Signature


BG:vs

cc: Bob Jones

O:\M035-SaltLake\S0350027-Bluffdale2\inspections\insp-10162008.doc



Location of GPS coordinates on file.



Road looking west from site.



Road looking east from site.



Old road disturbance in the middle.



Boulders just off the road.



Boulders just off the road.

